

Technical Support Guide: Understanding Tuner-Locked ECUs

What is a Tuner Lock?

A **tuner lock** occurs when a previous tuning shop or software platform restricts access to your vehicle's Engine Control Unit (ECU/PCM). This is typically done to protect proprietary tuning files.

Why is this a Problem?

When an ECU is locked, standard diagnostic and tuning tools cannot read, write, or modify the software. To perform any new custom tuning, diagnostic calibrations, or updates, the computer must first be completely reset to a factory state.

How to Resolve a Locked ECU

Option 1: Contact the Previous Tuner

- **The Process:** The specific hardware/account that locked the ECU is often the only software tool that can easily unlock it.
- **The Request:** Ask the original tuner to flash a 100% "stock" calibration file back onto the vehicle.

Option 2: Factory Dealer Reprogramming

- **The Process:** Take the vehicle to a dealership or an independent shop with factory-level programming tools.
- **The Request:** Request a "Full Module Flash" using official OEM software (such as GM SPS2, Ford IDS, or Chrysler wiTECH). This process completely overwrites the locked software through the OBD2 port.

Option 3: Bench-Flashing Service

- **The Process:** If the OBD2 port is completely blocked from flashing, the ECU must be physically removed from the vehicle.
- **The Request:** The module is sent to a specialized technical service to be manually wiped and reset on a workbench.

Option 4: ECU Replacement

- **The Process:** If the module cannot be overridden via the OBD2 port or through a bench-flash, it must be replaced.

- **The Request:** Purchase a new or clean, unlocked factory replacement computer and program it to your vehicle's VIN.
-

Next Steps for Service

If we have informed you that your vehicle's ECU is locked, please speak with your service advisor to determine which option best fits your timeline and budget so we can proceed with your service.